To: Pratt, David[Pratt.David@epa.gov]

From: Enders, Jhana

**Sent:** Mon 8/17/2015 9:05:07 PM

Subject: Re: EPA Report for Surface Water and Sediment Sampling - Team 2

Thanks David

Sent from my iPad

On Aug 17, 2015, at 3:03 PM, Pratt, David < Pratt. David@epa.gov > wrote:

Yes

From: Enders, Jhana

**Sent:** Monday, August 17, 2015 3:02 PM

To: Pratt, David

Subject: Re: EPA Report for Surface Water and Sediment Sampling - Team 2

so the horseshoe pond and the pond connected to it r both full?

Sent from my iPhone

On Aug 17, 2015, at 2:31 PM, Pratt, David < Pratt. David@epa.gov > wrote:

Jhana,

Site conditions were essentially the same as yesterday. The only real issue encountered was that the new water sampler was skimming the water surface when collecting the samples. The issue was addressed and fixed onsite.

Also, I noticed the two holding ponds at the water treatment plant are full now. I did not encounter any citizens during the site visits.

David

From: Enders, Jhana

Sent: Sunday, August 16, 2015 3:47 PM

To: Pratt, David

Subject: Re: EPA Report for Surface Water and Sediment Sampling - Team 2

Great! Thanks David.

Sent from my iPhone

On Aug 16, 2015, at 2:42 PM, Pratt, David < Pratt. David@epa.gov > wrote:

Report attached....

David

<Gold King Mine SpillAugust16.docx>